

TYPE OF CHECK:	engine + gear + chassis + paint only	DATE:	29/1/2026
CAR:	suzuki	TIME:	8.03pm
MODEL:	2015	COLOR:	black-96413
PLATE NO:	774050	90%	

body have scratches + bonnet have repaired + front glass changed before
front bumper have accident before + dent front bumper bracket at head chassis
dent at rear left head chassis + silencer have welding + change engine belt
front differentiol have welding + Change front oil seal grease knuckle
gear oil pan was open before + engine tune up + gear service
brake service + change engine mounting + adjust wheel alignment
special shock absorber&spring installed
paint : plastic kit + 1/4 bonnet + 1/4 front right fender



Customer Signature
Engine Power:

- المحرك على الكمبيوتر - الشاصي نظرياً - الجير عند القيادة
- المحل غير مسؤول عن أي أغراض داخل السيارة قد تفقد أثناء الفحص أو الإصلاح
- لا يوجد أي ضمان على السيارة بعد الفحص
- المحل غير مسؤول عن أي أعطال أثناء الفحص




State	DTC	Create Report
	* Immobilizer	
Present	-> 23 No ECU Code Transmitted From	
	* Meter	
History	-> B1810 Fuel Level Sensor Circuit / Open	Back ←



Diagnostic resulted

90.0%

75.%%	80.8 %	98.9%
<u>Minimum</u>	<u>Average</u>	<u>Maximum</u>



© GM Corp