



Suzuki Vehicle Diagnostic Report

Vehicle Information

--/Suzuki/Eritga/--
VIN: MA3NC2B10RA730266

Odometer Reading: 65621km
License Plate: --



Scan to download PDF

Customer Information

Name: -- Tel: --

Device information

Scanner: MaxiSys MS906MAX
Version: V3.10
Serial Number: V6BGRAC01816
Repair Order Number: V6BGRAC0181620260905163326551

System Scanned (11)

System	Status/DTC
ECM/PCM(Engine/powertrain)	✓ 0
TCM(Transmission Control Module)	✓ 0
ABS/ESP(Anti-lock Braking System / Electronic Stability Program)	✓ 0
SRS(Airbag)	✓ 0
IPC/MA(Instrument Panel Cluster (IPC)/meter/M&A)	✓ 0
TPMS(Tire pressure monitoring system)	✗ 2
CGW(Central gateway control module)	✓ 0
EPS(Power steering)	✓ 0
BCM(Body Control Module)	✗ 2
SMK(Immobilizer and/or keyless system)	✗ 2
LTS(Lighting and turn signal)	✓ 0

DTC (6)

TPMS(Tire pressure monitoring system) (2 DTCs)

DTC	Description	Status
B1A30	Right front tire pressure low	History
B1A32	Right rear tire pressure low	History

BCM(Body Control Module) (2 DTCs)

DTC	Description	Status
B1134	Remote controller battery low	History
B150A	Solar sensor circuit high	Current

SMK(Immobilizer and/or keyless system) (2 DTCs)

DTC	Description	Status
B1134	Remote controller battery low	History
B150A	Solar sensor circuit high	Current

Technician Notes

Customer name: _____

Technician: _____

Date: _____

Note: Please save a copy of this report for your records.