

Kashf inspection center (KASHF)



September, 2026 · Report #6757

91
/100

A




VEHICLE INFORMATION

CAR MAKE
MGYEAR OF MANUFACTURING
2025CURRENT MILEAGE
23,564VIN NO.
LSJWJ4W93SZ058900PLATE NUMBER
954060CAR OWNER NAME
Mr ZouheirORGANIZATION NAME
KASHF


AI SUMMARY

Overall condition: Very good, with a 91% rating and 70 of 72 assessed points rated very good; 2 points were rated good and none were rated bad. Major findings: Electrical, air conditioning, chassis, suspension, safety, road-test, and most body and engine/transmission items were rated very good; the engine percentage was recorded at 94%. Areas needing attention: The front bumper requires polishing to properly check the paint, and fault codes were recorded from the engine control, brake/ABS, communication or low-battery, and body-control systems. Suggested actions: Polish the front bumper for further paint checking, and read the attached fault codes; further inspection of the recorded systems is recommended.



Excellent

CONDITION



OVERALL RATING



Service & Maintenance History

Condition Chart	System Inspection	Very Good	Good	Bad
	Electric System			
	AC			
	Body and berd			
	Chassis Condition			
	Suspestion System			
	engine and gear			
	Safety system			
	Road Test			

Remarks

 Good

 Very Good

 Bad

 All Notes

All Notes

Body and berd

front bumper

- Front bumper need to polish to check paint properly

Body and berd

Notes :

- Body dent & scratches

engine and gear

Gear Condition

- Gear condition OK

engine and gear

Engine percentage

- 94%

engine and gear

Engine and gearbox fault testing with inspection devices

- Have fault code(s) from Engine control system ECM/PCM (see attached codes)
- Have fault code(s) from Brake or ABS system (see attached codes)
- Have fault code(s) from Lost communication or due to Low battery issues (see attached codes)
- Have fault code(s) from Body control system [body, mirror., door, screen, antenna] (see attached codes)



Electric System

Inspects the battery, lights, wiring, and other electrical components to ensure proper functionality.

kashf performs detailed inspection and assessment for the electrical systems and components , thanks to the experts and BOSCH diagnostic tools The inspection covers: Front lighting system Rear lighting systems Driver assisting systems 12V battery and alternator Car accessories

 Front Headlights	Very Good
 Rear lights	Very Good
 Battery Efficiency	Very Good
 Alternator motor	Very Good
 High voltage battery efficiency	N/A
 Screen and Radio	Very Good
 Horn	Very Good
 Wipers	Very Good
 Power Windows	Very Good
 Power Seats	Very Good
 Mirror test	Very Good
 Sun Roof \ Panorama	Very Good



AC

Checks the air conditioning system to ensure proper cooling, airflow, and overall performance.





Kashf performs detailed inspection and assessment for the Air condition and engine cooling components , thanks to the experts and BOSCH diagnostic tools The inspection covers: Air Condition and Compressor Heating system Engine cooling system Fluid leaks

 Control panel	Very Good
 Ac cooling performance	Very Good
 Heater performance	Very Good
 Ac Fan operation	Very Good
 Air conditioner performance	Very Good



Body and berd

The chassis is fully inspected for sedan



Kashf provides a comprehensive and accurate evaluation and inspection of the vehicle's exterior to ensure its safety and compliance with Kashf standards. The inspection is conducted using several methods, such as: Specialized visual inspection Paint and putty thickness measurement using specialized devices Artificial intelligence Vehicle history records and previous repairs This section covers the following points: Exterior vehicle parts Interior cabin condition Window and rear windshield
Roof Windows Sash

<i>i</i> Hood Bonnet	Very Good
<i>i</i> front left fender	Very Good
<i>i</i> front left door	Very Good
<i>i</i> rear left door	Very Good
<i>i</i> rear left fender	Very Good
<i>i</i> trunk door	Very Good
<i>i</i> Rear right fender	Very Good
<i>i</i> rear right door	Very Good
<i>i</i> front right door	Very Good
<i>i</i> front right fender	Very Good
<i>i</i> roof	Very Good
<i>i</i> front bumper Front bumper need to polish to check paint properly	Good
<i>i</i> rear bumper	Very Good
<i>i</i> Front Windshield	Very Good
<i>i</i> Rear Windshield	Very Good
<i>i</i> Door Rubber	Very Good

i Interior Condition

Very Good

Notes :

- Body dent & scratches



Chassis Condition

Chassis and frame are inspected for sedan

At Kashf we assess the main components of the car's Chassis and Structure to ensure there is no deviation in the chassis measurements and no distinct signs of repair on welding join marks. The inspection is performed via : Approved CCM tools Experts Visual Inspection The inspection covers : Chassis frame (4 sides) Front inner wheelhouse Roof panel reinforcement Front and rear chassis member Windows Rust Existence

At Kashf we assess the main components of the car's Chassis and Structure to ensure there is no deviation in the chassis measurements and no distinct signs of repair on welding join marks.

 Front Left Chassis Dimensions	Very Good
 Front Right Chassis Dimensions	Very Good
 Rear Left Chassis Dimensions	Very Good
 Rear Right Chassis Dimensions	Very Good
 Undercarriage condition	Very Good
 Front Frame	Very Good
 Rear Frame	Very Good
 Right Side Frame	Very Good
 Left Side Frame	Very Good
 Upper Frame	Very Good



Suspension System

The steering system ensures the driver can control the direction of the vehicle smoothly and safely. It includes components like the steering wheel, steering column, and linkages that connect to the wheels. sedan

Steering and Suspension systems are essential for every car , therefore Kashf performs the most important checks and inspections to assure the stability of the car and shortest braking distance using BOSCH inspection station. The inspection covers: Front shock absorbers Rear shock absorbers Steering rack and components Front and rear axles Bearing Wheels hubs Engine mounts

 Front Shock absorbers	Very Good
 Rear shock absorbers	Very Good
 Front bushings and scissors	Very Good
 Bushings and rear scissors	Very Good
 Steering Column	Very Good
 Front Cross member bumper	Very Good
 Rear Cross member bumper	Very Good
 Engine\Transmission Mounts	Very Good
 Front and rear stabilizer bars	Very Good
 Front axle condition	Very Good
 Rear axle case	N/A



engine and gear

The engine is being checked for sedan

Kashf performs detailed Power-train inspection and assessment for all types of Hybrid and Electric cars , thanks to the experts and BOSCH diagnostic tools. The inspection covers :
Onboard diagnostics High Voltage Battery efficiency and estimated lifetime Electric Motor and components 2-Way Voltage Inverter Charging System Cooling System



Gear Condition

- Gear condition OK

Very Good



Engine percentage

- 94%

Very Good



Engine Performance and Efficiency

Very Good



Engine and gearbox fault testing with inspection devices

- Have fault code(s) from Engine control system ECM/PCM (see attached codes)
- Have fault code(s) from Brake or ABS system (see attached codes)
- Have fault code(s) from Lost communication or due to Low battery issues (see attached codes)
- Have fault code(s) from Body control system [body, mirror., door, screen, antenna] (see attached codes)

Good



Fluid Leaks

Very Good



Coolant leak check

Very Good



Hybrid System

N/A



Suction shaft check

N/A



exhaust system

Very Good



Safety system

Checks the condition and performance of the brake pads, discs, and fluid to ensure safe stopping.

When it comes to braking and safety , Kashf makes sure that every single sensor and parts in the braking system and air-bag is functioning at the perfect condition and adhere to Kashf standards. The inspection covers: SRS Component Tires Braking components Seat belts Traction system



SRS Airbags System

Very Good



front tire condition

Very Good



Rear tire condition

Very Good



Wheel nuts

Very Good



Seat belt Condition

Very Good



Abs System

Very Good



Spare tire and tools

Very Good




Inspection Photos

Inspection Photos

Car Images



Inspection Images



Road Test

A driving test to evaluate the vehicle's performance, handling, and overall condition on the road.

Kashf professional team performs an advanced road-test to check the engine performance, wheel alignment, transmission shifts, transaxle, clutch, brakes, weird noises and car maneuvering. Also, the team inspects the car's known issues and technical errors found by the inspection team



Engine performance on the road

Very Good

 Engine performance on the road	Very Good
 Transmission performance on the road	Very Good
 Four wheel drive / Transfer case system	N/A
 Front differential performance	N/A
 Rear differential performance	N/A
 Tire Road	Very Good
 Brake system	Very Good
 cruise control	Very Good
 EV/Hybrid Mode Operation	N/A